ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: M07658 Client: Alaskan Copper Works

Date Received: 09/15/11 Project: Metro Self Monitor M07658, F&BI 109214

Date Extracted: 09/19/11 Lab ID: 109214-01 x10
Date Analyzed: 09/19/11 Data File: 109214-01 x10.054

Matrix: Water Instrument: ICPMS1 Units: ug/L (ppb) Operator: AP

Lower Upper Internal Standard: % Recovery: Limit: Limit: Germanium 80 60 125

Analyte: Concentration ug/L (ppb)

 Chromium
 596

 Nickel
 530

 Copper
 436

 Zinc
 13.8

ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank Client: Alaskan Copper Works

Date Received: Not Applicable Project: Metro Self Monitor M07658, F&BI 109214

Lab ID: Date Extracted: 09/19/11 I1-654 mb Date Analyzed: 09/19/11 Data File: I1-654 mb.050 Instrument: ICPMS1 Water Matrix: AP Units: ug/L (ppb) Operator:

Lower Upper Internal Standard: Limit: Limit: % Recovery:

Germanium 60 125 82

Concentration Analyte: ug/L (ppb) Chromium <1 Nickel <1 Copper <1 Zinc <1

ENVIRONMENTAL CHEMISTS

Date of Report: 09/22/11 Date Received: 09/15/11

Project: Metro Self Monitor M07658, F&BI 109214

QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 109213-01 1/10 (Matrix Spike)

Analyte	Reporting Units	Spike Level	Sample Result	Percent Recovery MS	Percent Recovery MSD	Acceptance Criteria	RPD (Limit 20)
Chromium	ug/L (ppb)	20	25.7	102 b	100 b	67-132	2 b
Nickel	ug/L (ppb)	20	<10	96 b	98 b	73-119	2 b
Copper	ug/L (ppb)	20	91.3	9 3 b	118 b	50-144	24 b
Zinc	ug/L (ppb)	50	258	103 b	100 b	46-148	3 b

Laboratory Code: Laboratory Control Sample

		Percent									
	Reporting	\mathbf{Spike}	Recovery	Acceptance							
Analyte	Units	Level	LCS	Criteria							
Chromium	ug/L (ppb)	20	94	66-135							
Nickel	ug/L (ppb)	20	95	67-134							
Copper	ug/L (ppb)	20	96	66-134							
Zinc	ug/L (ppb)	50	96	57-135							

ENVIRONMENTAL CHEMISTS

Data Qualifiers & Definitions

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probability.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb Analyte present in the blank and the sample.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht Analysis performed outside the method or client-specified holding time requirement.
- ${
 m ip}$ Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- ${
 m jl}$ The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- $\,$ nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve Estimated concentration calculated for an analyte response above the valid instrument calibration range. A dilution is required to obtain an accurate quantification of the analyte.
- vo The value reported fell outside the control limits established for this analyte.
- x The sample chromatographic pattern does not resemble the fuel standard used for quantitation.

109214		æ	SAI	MPLE CH	AIN OF C	UST	'OD'	M	E_	09	-/5	-//	_		A	TY
Send Report To Dev	z	mPso~		SAMPLER	S (signature)			—				Ē	P	age#_	ROUNI	of
Company ALASKAN	PROJECT NAME/NO. PO#					i i	Standard (2 Weeks)									
Address 628	METRO Self movitur m07658						Rush charges authorized by:									
Address 628 S. HALADED SV. City, State, ZIP SPATIE WA 98/34 Phone # 206-57/-6033Fax # 206-382-4309				REMARKS							0	SAMPLE DISPOSAL Dispose after 30 days Return samples Will call with instructions				
Phone #_=== 77		-	7501			_					77 0.			cau wi	ich mscr	demons
	_			ANALYSES REQUESTED												
Sample ID	Lab ID	Date	Time	Sample Ty	# of containers	TPH-Diesel	TPH-Gasoline	VOCs by 8260	SVOCs by 8270	HFS Constant			2		1	Votes
MO7658	0\	9/15/11	/:30	HZC) /					X						
	_						_	\perp		\perp						
			7				+			+						P. 1
			5				\dagger									
2		iii 													×	
							+									
-	-						+	-	\vdash	+	240				×	
,							+									
Friedman & Bruya, Inc.	Relinguished by	SIGNATUI	RE		PRINT	NAM	E		_انرسا	C	OMP.	ANY		D	ATE	TIME
3012 16th Avenue West (SERROD V Honge					HCW			19	15/11	3:012					
Seattle, WA 98119-2029 Ph. (206) 285-8282	m/a/am				- Whan Phan					FeBI			9/1		571	V
Fax (206) 283-5044 Received by:												7	_	(
FORMS\COC\COC.DOC		1			777			- 47			Samp	les r	eceiv	ed at	22	_°C

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

September 22, 2011

Gerald Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on September 15, 2011 from the Metro Self Monitor M07658, F&BI 109214 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU0922R.DOC